

Bonding

- occurs when 2 or more elements link together to create molecules.
- 2 types of bonds
 - I) ionic
 - II) covalent
 - A) pure covalent
 - B) polar covalent

- Reason atoms bond → Octet Rule

All elements "want" to have 8 valence e⁻'s (full s + p suborbital) - creates stability
(exception: H and He - only need 2 valence e⁻'s)

1) Ionic Bonding


- occur between a metal and a nonmetal

metals

- have low 1st ionization energies (easily give away their valence e⁻)
- become positively charged ions, CATIONS
charged atom

Ex)

Mg
atomic # 12
12p⁺ & 12e⁻
10e⁻



becomes a cation with a charge of +2.




Ex)

Ge
atomic # 32

$$32p^+ : 32e^-$$

- 4e⁻ lost
28e⁻



becomes the cation, Ge⁴⁺

Nonmetals

- have high electronegativities (really "want" other atom's e⁺'s.) - steal e⁻ from metals
- become negatively charged ions, ANIONS

Ex)

F
atomic # 9
9p⁺ : 9e⁻
+ 1e⁻
10e⁻

charge of -1

steal 1 e⁻

$1s^2 2s^2 2p^5 + 1$
has 7 val. e⁻ originally
now has 8 val. e⁻

becomes an anion

F¹⁻ or F⁻¹ or F⁻

Ex)

P
atomic # 15
15p⁺ : 15e⁻
+ 3e⁻
18e⁻

steal 3 e⁻
 $1s^2 2s^2 2p^6 \cancel{3s^2} \cancel{3p^3} + 3$
originally has 5 val e⁻
now has val. e⁻

becomes P³⁻ or P⁻³

Summary


- Metals lose valence e⁻ to become stable cations
- Nonmetals gain valence e⁻ to become stable anions
- The + cation is attracted to the - anion, forming the ionic bond

Using electron dot diagrams to show the forming of an ionic bond

e⁻ dot diagrams

use the symbol for the element & up to 8 dots surrounding it to represent the valence e⁻'s.


Ex)



Steps

- 1) Draw e⁻ dot diagrams for the metal & nonmetal.
- 2) Draw arrows to show the e⁻'s transferring from the metal to the nonmetal.
- 3) write the charges that form
- 4) write the formula for the new ionic molecule

Examples



Properties of Ionic Compounds

- 1) extremely strong bonds
- 2) high melting & boiling points
- 3) hard, crystalline solids
- 4) conduct electricity when molten or dissolved in solution